



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
GLENTILT ROAD	O/S 8	Damaging	Buttress roots growing within c/w - no kerbstones, would be extensively damaged upon road repair	Sorbus intermedia	Plant in new 800mm pit between middle of 8-6 (same as felled tree)	Liquidambar styraciflua 'Worpl
GLENTILT ROAD	O/S 20	Damaging	Kerbs absent - cannot replace without root damage, previously topped - poor structural condition	Fraxinus excelsior	Plant in new 800mm pit o/s 20 (same as felled tree)	Corylus colurna
GLENTILT ROAD	OPPOSITE 5	Dangerous	Previously topped - poor structural condition, weakly attached regrowth on decaying topping points	Fraxinus excelsior	Plant in new 800mm pit opp 5 (same as felled tree)	Corylus colurna
GLENTILT ROAD	OPPOSITE 1	Dangerous	Previously topped - poor structural condition, weakly attached regrowth on decaying topping points	Fraxinus excelsior	Plant in new 800mm pit opp 1 (same as felled tree)	Liquidambar styraciflua 'Worpl
GLENTILT ROAD	O/S 1	Damaging	Buttress roots growing within c/w - no kerbstones, would be extensively damaged upon road repair	Platanus x hispanica	Plant in new 800mm pit o/s 1 (same as felled tree)	Liquidambar styraciflua 'Worpl
GLENTILT ROAD	O/S 24	Damaging	Kerbs pushed into c/w by buttress root pressing immediately on kerb rear - cannot realign	Sorbus intermedia	Plant in new 800mm pit o/s 24 (same as felled tree)	Liquidambar styraciflua 'Worpl
GLENTILT ROAD	O/S 33	Damaging	Kerbs pushed into c/w by buttress root pressing immediately on kerb rear - cannot realign	Sorbus intermedia	Plant in new 800mm pit o/s 33 (same as felled tree)	Liquidambar styraciflua 'Worpl